Uttaranchal

1. Kutumbari Temple, Dwarahat, Tehsil Ranikhet, Distt. Almora
2. Khera Ki Bandi, Old Cemetery, Tehsil Roorkee, Distt. Haridwar
3. Remains of ancient buildings locally identified with Vairatapattana, Dhikuli, Tehsil Ramnagar, Distt Nainital

Uttar Pradesh

1. Closed Cemetery, Katra Naka, Tehsil Banda, Distt. Banda
2. Large ruined site called Sandi Khera, Pali, Tehsil Shahabad, Distt. Hardoi
3. Cemetery, Jalaun (Bus Stand), Tehsil Jalaun, Distt. Jalaun
4. Gunner Burkill's Tomb, Rangaon, Tehsil Mehroni, Distt. Lalitpur
5. Imambara Amin-ud Daula, Lucknow, Tehsil Lucknow, Distt. Lucknow
6. Three Tombs, Lucknow-Faizabad Road at miles 3, 4 & 5, Tehsil Lucknow, Distt. Lucknow
7. Cemeteries at miles 6 & 7, Jahraila Road, Tehsil Lucknow, Distt. Lucknow
8. Cemetery at Gaughat, Lucknow, Tehsil Lucknow, Distt Lucknow

Cracks in palace of Ahom Kings in Assam

3116. SHRI BIRENDRA PRASAD BAISHYA: Will the PRIME MINISTER be pleased to state:

(a) whether the Ministry is aware that due to constant vibrations of the heavy machinery of power generating units at Nazira Thermal Power Station it is reported that large cracks has developed at 'Karenghar Ghar' the palace of Ahom Kings in Assam;

(b) the strong public resentment caused due to poor quality of building materials having been used in repairing other parts of the same building; and

(c) the important measures and initiative taken by Government of Assam and Central Government to preserve the palace of Ahom Kings which is a major tourist attraction of both local and foreign tourists?

THE MINISTER OF STATE IN THE MINISTRY OF PARLIAMENTARY AFFAIRS (SHRI V. NARAYANASAMY): (a) No, Sir. However, minor cracks have been noticed at Karenghar in plaster which are due to old age and peculiar climatic conditions of this region like heavy rainfall and moderately high temperature. The monument is absolutely safe and stable.

(d) To maintain authenticity and integrity of the monument, only original materials are used while carrying out any repairs to it.

(c) Tourist amenities like toilet block, drinking water facilities, pathways have been provided. Besides, a garden has also been developed. The monument is in good state of preservation.